


Coring Run 01FB



- ① PCTB is lowered into hole
- ② Pump turned on
- ③ Coring begins
- ④ Coring continues, but no penetration
- ⑤ Flow rate increased in effort to restart penetration
- ⑥ Coring ends
- ⑦ Flow rate reduced
- ⑧ Bit pulled up
- ⑨ PCTB is actuated, applying pressure boost and sealing the pressure section
- ⑩ PCTB is pulled out of hole

Coring Run 01FB

