


### Coring Run 05CS



- ① PCTB is lowered into hole
- ② Pump turned on
- ③ Coring begins
- ④ Coring continues, but no penetration
- ⑤ Coring ends
- ⑥ Flow rate reduced
- ⑦ Bit pulled up
- ⑧ PCTB is actuated, pressure boost is applied but lost
- ⑨ PCTB is pulled out of hole, pressure section unsealed

### Coring Run 05CS

