



# UT-GOM2-1-H005-1FB

as cut




# UT-GOM2-1-H005-2FB

as cut




# UT-GOM2-1-H005-3FB

as cut



# UT-GOM2-1-H005-4FB


as cut



# UT-GOM2-1-H005-5FB

as cut


liner lengths do not match scan as core moved during cuts



# UT-GOM2-1-H005-6FB


as cut

scanned again after temporary pressure drop



# UT-GOM2-1-H005-7FB


as cut



# UT-GOM2-1-H005-8FB


as cut

liner lengths do not match scan as core moved during cuts




# UT-GOM2-1-H005-9FB

as cut (Q4000 data)




# UT-GOM2-1-H005-10FB

as cut



# UT-GOM2-1-H005-11FB

as cut



# UT-GOM2-1-H005-13FB

as cut

