

Coring Test	Configuration	Core Name	Pressure chamber sealed?	Coring begin depth (ft)	Coring stop depth (ft)	Penetration (ft)	Core recovered (ft)	Recovery (%)	Flow Rate (gal/min)	Date	Coring start time	Coring end time
1	Cutting shoe	COK-01CS	Y	Act. test	1482	-	-	-	0	4/14/2021	13:15	14:20
2	Cutting shoe	COK-02CS	Y	Act. test	1482	-	-	-	0	4/14/2021	14:30	15:20
3	Cutting shoe	COK-03CS	Y	Act. test	1482	-	-	-	180, 320	4/14/2021	15:30	17:20
4	Cutting shoe	COK-04CS	Y	1553	1557.2	4.2	0	0.0%	230, 310	4/15/2021	10:48	11:44
5	Cutting shoe	COK-05CS	Y	1557.2	1566	8.8	5.58	63.4%	450	4/15/2021	1:17	2:32
6	Cutting shoe	COK-06CS	Y	1566	1569.2	3.2	0.33	10.3%	450	4/15/2021	15:46	16:26
7	Cutting shoe	COK-07CS	N	1569.2	1574	4.8	0	0.0%	450, 500, 550	4/16/2021	9:10	10:26
8	Cutting shoe	COK-08CS	Y	1574	1579.2	5.2	0.5	9.6%	450, 500	4/16/2021	11:47	12:48
9	Cutting shoe	COK-09CS	N	1579.2	1583.7	4.5	1.2	26.7%	450, 500	4/16/2021	14:05	14:57
10	Cutting shoe	COK-10CS	Y	1583.7	1589.4	5.7	2.83	49.6%	315	4/17/2021	10:51	12:13
11	Cutting shoe	COK-11CS	Y	1589.4	1595.5	6.1	0.25	4.1%	315	4/17/2021	13:25	14:40
12	Face bit	COK-12FB	Y	Act. test	1574	-	-	-	320	4/18/2021	10:00	10:50
13	Face bit	COK-13FB	Y	1595.5	1598.7	3.2	0	0.0%	320	4/18/2021	11:42	12:42
14	Face bit	COK-14FB	Y	1598.7	1605.8	7.1	8.9	125.4%	310, 200	4/18/2021	13:46	14:51
15	Face bit	COK-15FB	Y	1605.8	1611.1	5.3	4	75.5%	300	4/19/2021	9:02	9:48
16	Face bit	COK-16FB	Y	1611.1	1617.8	6.7	4.4	65.7%	300	4/19/2021	10:55	11:43
17	Face bit	COK-17FB	N	1617.8	1619.1	1.3	1.1	84.6%	320	4/19/2021	17:11	17:31
18	Face bit	COK-18FB	Y	1619.1	1622.6	3.5	3.25	92.9%	310	4/20/2021	9:06	9:34
19	Face bit	COK-19FB	Y	1622.6	1629	6.4	5.6	87.5%	310, 285	4/20/2021	10:37	11:32